ADA 085 627

ON ADIABATIC SHEAR BAND DETERMINATIONS BY SURFACE OBSERVATIONS

TECHNICAL LIBRARY

MICHAEL R. STAKER
PROCESS DEVELOPMENT DIVISION

March 1980

Approved for public release; distribution unlimited.

ARMY MATERIALS AND MECHANICS RESEARCH CENTER Watertown, Massachusetts 02172

The findings in this report are not to be construed as an official Department of the Army position, unless so designated by other authorized documents.

Mention of any trade names or manufacturers in this report shall not be construed as advertising nor as an official indorsement or approval of such products or companies by the United States Government.

DISPOSITION INSTRUCTIONS

Destroy this report when it is no longer needed.

Do not return it to the originator.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
AMMRC TR 80-6		
4. TITLE (and Subtitle)		5. TYPE OF REPORT & PERIOD COVERED
ON ADIABATIC SHEAR BAND DETERMINATIONS BY SURFACE OBSERVATIONS		Final Papart
		Final Report 6. PERFORMING ORG. REPORT NUMBER
		The state of the s
7. AUTHOR(a)		8. CONTRACT OR GRANT NUMBER(s)
Michael R. Staker		
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
Army Materials and Mechanics Research Center		D/A Project: 1L162105AH84
Watertown, Massachusetts 02172		AMCMS Code: 612105.H840011
DRXMR - ER 11. CONTROLLING OFFICE NAME AND ADDRESS		Agency Accession: DA 0G4768
U. S. Army Materiel Development and Readiness		March 1980
Command, Alexandria, Virginia 22333		13. NUMBER OF PAGES
		6
14. MONITORING AGENCY NAME & ADDRESS(if different from Controlling Office)		15. SECURITY CLASS. (of this report)
		Unclassified
		15a DECLASSIFICATION DOWNGRADING SCHEDULE
ĺ		SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)		
Approved for public release; distribution unlimited.		
Approved for public forease, distribution untimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
Submitted to Scripta Metallurgica		
19. KEY WORDS (Continue on reverse side if necessery an	d identify by block number)	
Adiabatic Fracti	ıre	
	xplosives	ŀ
Fragmentation		51
20. ABSTRACT (Continue on reverse side if necessary end identify by block number)		
(ann neuman arne)		
(SEE REVERSE SIDE)		
		İ

UNCLASSIFIED SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

Block No. 20

ABSTRACT

Two cracking mechanisms, adiabatic shear band cracking and ductile dimpled shear cracking, have been observed in hollow, right circular cylinders of AISI 4340 steel, which were explosively expanded in a quick-stop containment apparatus. It is concluded that distinction of cracking mechanisms cannot be made without the use of metallographic sectioning, as the external appearances of both types of cracks are identical. These exploding cylinder results demonstrate the inaccuracies associated with determining the presence or density of adiabatic shear bands only from surface observations.

INTRODUCTION

Detonation of high explosives within hollow cylinders leads to fragmentation by several fracture modes. 1-5 Understanding these fragmentation processes can benefit the field of ordnance. Recent use of the "contained fragmenting round" technique 5,7 to study one of these fracture modes (adiabatic shear band formation and subsequent separation) has not focused on the criteria for the onset of adiabatic shear. A study of the adiabatic shear band mechanism should indicate how material properties influence both the onset and propagation of shear bands. The purpose of this paper is to report initial results of a study of the adiabatic shear band mechanism, where it was possible to distinguish two cracking mechanisms in the same alloy with different heat treatments.

MATERIALS AND EXPERIMENTAL PROCEDURE

Hollow, right circular cylinders of AISI 4340 steel (28.6 mm I.D., 41.3 mm O.D., 102 mm long) were used to study adiabatic shear band formation by means of the "contained fragmenting round" technique. Chemical composition in weight percent was 0.41 C, 1.84 Ni, 0.83 Cr, 0.26 Mo, 0.84 Mn, 0.26 Si, 0.15 Cu, 0.009 P, 0.012 S, balance Fe. The specimens were heat treated by austenitizing in a salt bath at 843 C for 1/2 hour, and oil quenched and tempered for 1 hour.

This quick-stop technique is described by Erlich et al.^{6,7} but, briefly, it consists of a large, outer thick-walled containment cylinder surrounding the hollow right cylindrical specimen which is loaded with high explosive (C-4 at a density of 1.65 g/cc) and separated from the containment cylinder by a buffer layer of a castable polymerized methyl methacrylate (Figure 1). A cast-in-place lead cylinder surrounds the containment cylinder and acts as a trap to carry momentum radially away from the specimen. The compressive wave from detonation travels outward and enters the lead cylinder, but as reflection occurs at the outer diameter of the lead cylinder, the ingoing tensile wave stretches the lead cylinder and carries momentum away, minimizing damage to the specimen. As the specimen expands, the buffer layer is compressed, preventing an impact against the containment cylinder. The thickness of the buffer layer controls the amount of radial expansion of the specimen. Use of a tapered buffer layer allows a variation in strain within one specimen.

- 1. WALSH, B. E., and BEDFORD, A. J. Effect of Taper on the Natural Fragmentation of Medium Carbon Steel Cylinders. Materials Research Lab., Report MRL-R-704, Australia, January 1978 (AD BO 35 280.L).
- 2. BEETLE, J. C., RINNOVATORE, J. V., and CORRIE, J. D. Fracture Morphology of Explosively Loaded Steel Cylinders in Scanning Electron Microscopy Proc. of 4th Annual SEM Symp., IIT Research Inst., Chicago, IL, April 1971.
- CLARK, E. N., and JURIACO, I. P. Mechanics of Fragmentation of Cylinders in Proceedings of the Army Symposium on Solid Mechanics - The Role of Mechanics in Design - Ballistic Problems, p. 331, Army Materials and Mechanics Research Center, AMMRC MS 73-2, September 1973 (AD 77 28 27).
- 4. A Co-Operative Research and Development Project. Fracture Mechanisms in Naturally Fragmenting Materials. Report MOU/FM/1, October 1975, p. 34 (AD BO12485L).
- 5. BEDFORD, A. J. The Natural Fragmentation of Steel Cylinders with Tempered Martensite Microstructures. Defense Standards Lab., Report 532, Australia, December 1972 (AD 912311).
- ERLICH, D., SEAMAN, L., SHOCKEY, D., and CURRAN, D. Development and Application of a Computational Shear Band Model. SRI International, Contract DAAD05-76-C-0762, Final Report, U.S. Army Ballistic Research Laboratories, Aberdeen Proving Ground, MD, May 1977.
- 7. ERLICH, D., CURRAN, D., and SEAMAN, L. Further Development of a Computational Shear Band Model. SRI International, Contract DAAG46-77-C-0043, Final Report (Draft Form), Army Materials and Mechanics Research Center, September 1978.




Figure 1. Cross-section diagram of contained fragmenting round experiments with 4340 steel specimen in place. The buffer layer thickness B is in the range of 1.5 mm, but varies from experiment to experiment, and may be double at the top.

Several material properties, including a range of hardnesses obtained by heat treatment, were investigated to explore the propensity for adiabatic shear band formation. AISI 4340 steel was used because of its potential for a variety of material properties obtainable by heat treatment, which are well documented in the literature. Of the two specimens in this study, one was tempered at 427 C (S-2) and one at 649 C (S-3). The final hardness for S-2 was HRC 43 and for S-3, HRC 27. Each specimen was explosively expanded in the containment fixture causing axial cracks to form.

RESULTS AND DISCUSSION

Two specimens with different heat treatments are shown in Figure 2 after explosive expansion in the contained fragmenting round fixture. The effect of the tapered buffer layer, to produce an end-to-end strain gradient, is evident in Figure 2a. Cracking can be seen on the inside surfaces of the specimens (Figure 2b). These cracks, when viewed from the surface, appear the same for both hardnesses. Sections through the wall thickness reveal cracking at approximately 45° to the radial and hoop directions for both specimens (Figure 2c). However, there are clear differences in the deformation and fracture mechanisms of each specimen. Specimen S-2, the harder material, exhibits white layering with cracking along this surface. This is taken as direct evidence of adiabatic shear deformation and has been called transformation adiabatic shear.^{8,9} This is in contrast to S-3, the softer specimen, in which there is no evidence of white layering nor deformation adiabatic shear bands (Figure 2c). Flow lines concentrating to a curved narrow band would be evidence of deformation adiabatic shear.8,9 This division of adiabatic shear bands into two types was proposed on the basis of etching characteristics and hardness. There is, at this time, not enough crystallographic evidence to indicate that they are different structures. could both be highly deformed matrix structures, and the degree of deformation alone would account for the etching and hardness differences.

^{8.} BACKMAN, M. E., and FINNEGAN, S. A. The Propagation of Adiabatic Shear in Metallurgical Effects at High Strain Rates, R. W. Rohde, B. M. Butcher, J. R. Holland, and C. H. Karnes, ed., Plenum Press, New York, 1973, p. 531.

^{9.} ROGERS, H. C. Adiabatic Plastic Deformation. Ann. Rev. Mater. Sci., v. 9, 1979, p. 283.




Figure 2. Specimens after detonation showing (a) each specimen post mortem and (b) the inside diameter surfaces with cracking and (c) polished and etched cross sections of each wall. Specimen S-2 shows adiabatic shear bands and specimen S-3 shows ductile dimpled shear. The axial (A), hoop (H), and radial (R) directions are indicated.

Fracture in S-2 was by cracking along adiabatic shear bands (determined by metallographic sections) and S-3 shows ductile dimpled shear cracking (determined by metallographic sections and scanning electron microscopy). As can be seen from Figure 2b, both modes of cracking appear the same on the surface and therefore distinction must be made by sectioning and metallographic examination.

The orientation of both cracking modes is the same in both mechanisms, and no external appearances suggest any distinction. This lack of distinguishability by external appearance is in contrast to the two deformation mechanisms plugging and bulging, observed in 4340 steel by Mescall and Papirno¹⁰ in ballistic penetration of targets by hard projectiles. Ballistic impact of their soft (HRC 15) target resulted in extensive bulging at the area of impact without any accompanying adiabatic shear. This is in contrast to their observations on the harder (HRC 52) target in which the bulging was replaced by localized deformation and white layering, leading to a shearing out of a plug roughly the diameter of the projectile. Unlike the exploding cylinder test, observations of the external geometry of ballistically impacted targets sometimes indicate whether adiabatic shear takes place.

These exploding cylinder results demonstrate the inaccuracies associated with determining the presence or density of adiabatic shear bands only from surface observations.^{6,7} The nucleation criteria are expected to be different for ductile shear cracks and adiabatic shear bands. These two criteria are governed by different material properties and therefore vary in different functional relation to changes in these properties. Current theoretical analysis by the author shows adiabatic shear banding is governed by achievement of a critical true shear strain which, in turn, is a function of the temperature sensitivity of the flow stress of the alloy, its work hardening exponent, and the volume specific heat. The onset of ductile shear cracking is independent of temperature sensitivity of strength and volume specific heat.

CONCLUSIONS

- 1. Two cracking mechanisms, adiabatic shear band cracking and ductile dimpled shear cracking, have been observed in hollow, right circular cylinders of AISI 4340 steel, which were explosively expanded in a quick-stop containment apparatus.
- 2. Distinction of cracking mechanisms cannot be made without the use of sectioning and metallographic examination as the external appearances of both types of cracks are identical.

ACKNOWLEDGMENTS

The author wishes to thank Mr. J. Mescall and Drs. F. R. Larson and M. Azrin for valuable discussions. The explosive work was performed by Mr. C. J. Polley.

10. MESCALL, J., and PAPIRNO, R. Spallation in Cylinder-Plate Impact. Exper. Mech, v. 14, 1974, p. 257.

```
DISTRIBUTION LIST
No. of
                                           Tο
Copies
    Office of the Under Secretary of Defense for Research and Engineering, The Pentagon,
     Washington, D.C. 20301
    Commander, Defense Technical Information Center, Cameron Station, Building 5,
     5010 Duke Street, Alexandria, Virginia 22314
    Director, Defense Advanced Research Projects Agency, 1400 Wilson Boulevard,
     Arlington, Virginia 22209
     Metals and Ceramics Information Center, Battelle Columbus Laboratories,
     505 King Avenue, Columbus, Ohio 43201
  2 ATTN: Mr. Daniel Maykuth
     Deputy Chief of Staff for Research, Development, and Acquisition, Headquarters,
     Department of the Army, Washington, D.C. 20310
    ATTN: DAMA-ARZ
            Dr. Bernard R. Stein
     Commander, U.S. Army Materiel Development and Readiness Command,
     5001 Eisenhower Avenue, Alexandria, Virginia 22333
     ATTN: DRCDE-DE, Development Division
            DRCDE-RS, Research Division
            DRCDE-RS, Scientific Deputy
  1
  1
            DRCLDC
     Commander, U.S. Army Aviation Research and Development Command, P.O Box 209,
     Main Office, St. Louis, Missouri 63166
     ATTN: DRDAV-LEP, Mr. J. M. Thorp
            DRDAV-ER, Dr. I. Peterson
     Commander, U.S. Army Missile Command, Redstone Arsenal, Alabama 35809
     ATTN: DRSMI-IE, Mr. J. E. Kirshtein
            DRSMI-R, Mr. John L. McDaniel
            DRSMI-TB, Redstone Scientific Information Center
  1
            Chief Scientist, Dr. W. W. Carter
  1
  1
            Directorate of R&D
  1
            Dr. B. Steverding
     Commander, U.S. Army Troop Support and Aviation Materiel Readiness Command,
     4300 Goodfellow Boulevard, St. Louis, Missouri 63120
     ATTN: DRSTS, Mr. J. Murphy
     Commander, U.S. Army Armament Research and Development Command,
     Dover, New Jersey 07801
```

ATTN: DRDAR-SCM, J. D. Corrie 2

Technical Library

Mr. Harry E. Pebly, Jr., PLASTEC, Director

Commander, U.S. Army Tank-Automotive Research and Development Command,

Warren, Michigan 48090

ATTN: DRDTA-PPS, Mr. David Siegel DRDTA-RCM.1, Mr. Edward Moritz DRDTA-RCM.1, Mr. Donald Phelps 1

Commander, Aberdeen Proving Ground, Maryland 21005

ATTN: Technical Library, Building 313

Commander, U.S. Army Foreign Science and Technology Center, 220 7th Street, N.E., Charlottesville, Virginia 22901

1 ATTN: DRXST-MT1

1

1

Commander, Rock Island Arsenal, Rock Island, Illinois 61299

ATTN: SARRI-LEP-L

Director, Eustis Directorate, U.S. Army Air Mobility Research and Development Laboratory, Fort Eustis, Virginia 23604

ATTN: Mr. J. Robinson, DAVDL-E-MOS (AVRADCOM)

Director, U.S. Army Ballistic Research Laboratories, Aberdeen Proving Ground, Maryland 21005

ATTN: Dr. D. Eichelberger DRDAR-TSB-S (STINFO)

Mr. B. G. Achhammer

Mr. G. C. Deutsch, Code RW

National Aeronautics and Space Administration, Lewis Research Center, 21000 Brookpark Road, Cleveland, Ohio 44135

1 ATTN: Library

1

National Aeronautics and Space Administration, Marshall Space Flight Center, Huntsville, Alabama 35812

ATTN: R. J. Schwinghamer, EHOl, Dir., M&P Lab

Mr. W. A. Wilson, EH41, Bldg. 4612

Albany Metallurgy Research Center, Albany, Oregon 97321

1 ATTN: Mr. A. H. Roberson, Research Director

Defense Materials Service, General Services Administration, Washington, D.C. 20405 1 ATTN: Mr. Clarence A. Fredell, Director, Technical R&D Staff

General Dynamics, Convair Aerospace Division, P.O. Box 748, Fort Worth, Texas 76101 ATTN: Mfg. Engineering Technical Library

Cabot Corporation, Machinery Division, P.O. Box 1101, Pampa, Texas 79065

1 ATTN: W. L. Hallerberg, Director of Metallurgy

Director, Army Materials and Mechanics Research Center, Watertown, Massachusetts 02172

2 ATTN: DRXMR-PL 1 DRXMR-WD 1 Author

UNCLASSIFIED UNLIMITED DISTRIBUTION Key Words Adiabatic Shear properties Fragmentation g and ductile dimpled shear r cylinders of AISI 4340 steel, Imment apparatus. It is con- be made without the use of s of both types of cracks are ate the inaccuracies associated shear bands only from surface
Army Materials and Mechanics Research Center, Matertoun, Massachusetts 02172 WALLASSIFIED ON ADIABATIC SHEAR BAND OETERNINATIONS BY ON ADIABATIC SHEAR BAND OETERNINATIONS BY SURFACE OBSERVATIONS.—Michael R. Staker Technical Report AWMRC TR 80-6, March 1980, 6 pp - AMMONS Code 612105.H840011 Two cracking, have been observed in hollow, right circular cylinders of AISI 4340 steel, which were explosively expanded in a quick-stop containment apparatus. It is convoluded that distinction of cracking mechanisms cannot be made without the use of metallographic sectioning, as the external appearances of both types of cracks are identical. These exploding cylinder results demonstrate the inaccuracies associated with determining the presence or density of adiabatic shear bands only from surface observations.
UNCLASSIFIED UNLIMITED DISTRIBUTION Key Words Adiabatic Shear properties Fragmentation in cylinders of AIS1 4340 steel, inment apparatus. It is con- is be made without the use of so footh types of cracks are so footh types of cracks are ate the inaccuracies associated shear bands only from surface
Ammy Materials and Mechanics Research Center, Matertown, Massachusetts ON ADIABATIC SHEAR BAND DETERNINATIONS BY SURFACE OBSERVATIONS - Michael R. Staker Technical Report AMMRC TR 80-6, March 1980, 6 pp - Adiabatic Adiabatic AMCMS Code 612105.H840011 Two cracking mechanisms, adiabatic shear band cracking and ductile dimpled shear cracking, have been observed in hollow, right circular cylinders of AISI 4340 steel, which were explosively expanded in a quick-stop containment apparatus. It is concluded that distinction of cracking mechanisms cannot be made without the use of metallographic sectioning, as the external appearances of both types of cracks are identical. These exploding cylinder results demonstrate the inaccuracies associated with determining the presence or density of adiabatic shear bands only from surface observations.